DAMS WITH IDENTIFIED SAFETY DEFICIENCIES

Arizona Department of Water Resources Office of Water Engineering Dam Safety

Friday, July 29, 2005

Friday, July 29, 2005

Page 1 of 6

	A	pa	C	he
--	---	----	---	----

SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
01.36 Luna	Significant	Luna, New Mexico	8.00		
					EAP
Cochise					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
2.03 Apache Station Ash/Scrubber WDF	High	N/A	0.00	03/10/2004	
					EAP
Coconino					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
3.02 West Cataract Creek	Significant	Williams	2.00		
					EAP
					Outlet Works
3.10 Dogtown	Significant	Havasupai Indian Reservation & I-40	110.00	07/07/2001	
					EAP
					Outlet Works
3.44 Continental #1	High	Flagstaff	2.00	07/06/2005	
					EAP
3.47 Odell	Significant	Pinewood & Munds Park	0.20		
					EAP
3.59 Flagstaff Reservoir West	High	Residences	0.05	12/14/2001	
					EAP
					Embankment
Graham					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
05.04 Cluff Ranch #3	Significant	Dublin & Pima	6.00		

Friday, July 29, 2005

					LAF
05.10 Lebanon Reservoir #1 (Upper)	Significant	Safford	13.00		
					Embankment
					Other
					Outlet Works
05.14 Judy Wash Retarding	High	Solomon	1.00		
					No Safety Deficiencies
05.17 Freeman Wash Retarding	High	Thatcher	1.00		
					Emergency Spillway
05.23 Haralson	High	Thatcher	4.00		No Safety Deficiencies
05.24 Grant Morris	High	Thatcher	2.00		No daicty Delicionolos
03.24 GIAIR MOINS	riigii	Hatorici	2.00		EAP
05.25 Howard	High	Pima	3.00		
					EAP
05.26 Chesley-Wamslee	High	Pima	3.00		
					EAP
05.28 No Name Wash	High	Lone Star	2.00	06/30/1999	
					Foundation
05.29 Lee	High	Eden	5.00		EAP
05.31 Billingsley	High	Eden	2.00		LAI
US.ST Billingsley	піgп	Edell	2.00		EAP
05.33 Cook Reservoir	High		0.00	06/22/2001	
	o o				EAP
					Embankment
					Emergency Spillway
					Outlet Works

EAP

Friday, July 29, 2005

SID Dam Name	Hazard Class	s Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
07.21 McMicken	High	Surprise	0.50		
					Embankment
					Emergency Spillway
					Foundation
					Outlet Works
07.23 Camp Dyer Diversion	Significant	Sun City	18.00	03/19/2002	
					EAP
07.28 White Tanks #3	High	Litchfield Park	0.25		
					Emergency Spillway
07.29 White Tanks #4	High	Goodyear	8.00		
					Embankment
					Emergency Spillway
					Outlet Works
07.35 West Park	High	Phoenix	0.00	05/04/2001	
					EAP
07.36 East Park	High	Phoenix	0.00	05/04/2001	
					EAP
07.47 North Mountain Flood Detention #3	High	Phoenix	0.00	04/24/2001	
					EAP
07.50 Spook Hill	High	Mesa	7.00	05/13/1986	
					Embankment
07.51 Phoenix Detention Basin #7	High	Phoenix	0.00	10/22/1985	
					EAP
					Embankment
07.59 Thunderbird Park Reservoir	High	Glendale	0.00	12/04/2003	
					EAP

Friday, July 29, 2005

Page 4 of 6

Other

Mohave

SID	Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
08.09 S	hort Creek Southside #2	Significant	Colorado City	1.00	07/09/2001	
						EAP
08.10 S	hort Creek Southside #1	High	Colorado City	1.00	07/09/2001	
						EAP
08.11S	tockton Hill	Significant	Kingman	2.00	09/03/2002	
						EAP
						No Safety Deficiencies

Navajo

SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
09.11 Daggs	High	Taylor	8.00		
					Embankment
					Emergency Spillway
09.14 Scott	Significant	Jaques Dam & Show Low	5.00	12/12/1989	
					EAP
					Outlet Works
09.16Lakeside	Significant	Show Low	7.00		
					EAP
09.18 Woodland	High	Pinetop & Lakeside	3.00	07/15/1994	
					EAP
09.19 Fool Hollow	High	Taylor	14.00	06/24/1981	
					EAP
					Emergency Spillway
09.20 Black Canyon	High	Heber & Overgaard	9.90	08/13/2002	

Friday, July 29, 2005

Page 5 of 6

					EAP
					Emergency Spillway
09.28 Cholla Fly Ash Pond	High	Joseph City	5.00	12/10/1998	
					Embankment
09.30 Trophy Lake	Significant	Taylor	9.00	05/01/2001	
					EAP
					Embankment
Santa Cruz					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
12.05 Pena Blanca	Significant	Rio Rico	10.00	05/19/1978	
					EAP
Vayanai					
Yavapai					
SID Dam Name	Hazard Class	Nearest Downstream Development	Miles	Owner Notified	Safety Deficiencies:
	Hazard Class	Nearest Downstream Development Granite Dells	<i>Miles</i> 10.00	Owner Notified 09/09/1980	Safety Deficiencies:
SID Dam Name					Safety Deficiencies: Concrete
SID Dam Name					
SID Dam Name					Concrete
SID Dam Name					Concrete Emergency Spillway
SID Dam Name					Concrete Emergency Spillway Foundation
SID Dam Name 13.13 Willow Creek	High	Granite Dells	10.00	09/09/1980	Concrete Emergency Spillway Foundation
SID Dam Name 13.13 Willow Creek	High	Granite Dells	10.00	09/09/1980	Concrete Emergency Spillway Foundation Other

Friday, July 29, 2005

Page 6 of 6